

Appendix C
Site Inspection and Photographs

Page intentionally blank

MEMORANDUM FOR RECORD

30 November 2007

SUBJECT: FN 200702061 Site Visit to Proposed Community Dock Location for The Cliffs Subdivision

DATE: 29 November 2007

1. A site visit was completed to determine existing environmental conditions and layout of proposed structure in relation to size of main channel of Boone Lake at subject location.
2. Site was accessed by water. David Robinson and I visited the site by parking a boat at several sites along the shoreline and walking to different points along the proposed development. No construction has begun on shoreline at the proposed site.
3. Shoreline throughout the area for the proposed community docks is lined with woody vegetation consisting mainly of oak, cedar, and sycamore trees. No evidence of springs or wetlands was found during the inspection.
4. Pictures are attached that show site conditions and also show dimensions of the lake where the docks are proposed.
5. The site visit did not reveal any issues or areas of concern regarding processing of the request or issuance of the permit.

Travis Wiley
Project Manager
Regulatory Branch



Approximate upstream end of Dock C.
Approximately 627' across lake at this point.



Approximate upstream end of Dock B. Lake is
approximately 606' wide at this point



Approximate upstream end of Dock A. Lake is approximately 639' wide at this point.



Location of upstream property boundary line.

Page intentionally blank